

? 37/ ??????? ?3

 C 701 (9,21 z) ф1.75 - 70шт	 C 702 (3,64 z) ф1 - 94шт	 C 703 (3,19 z) ф1.75 - 8шт	 C 704 (11,78 z) ф1.75 - 8шт, Кв 12 - 2шт
 C 705 (4,91 z) ф 3.5 - 6шт, ф 2.5 - 8шт	 C 706 (3,34 z) ф3.0 - 2шт	 C 707 (5,1 z) ф1.25 - 16шт, Ж 3 - 2шт	 C 708 (5,1 z) ф1.25 - 16шт, Кв 2x2 - 2шт
 C 709 (7,4 z) ф1.75 - 92шт	 C 710 (20,85 z) ф1.25 - 108шт, ф1.5 - 6шт	 C 711 (4,4 z) Ж 5 - 2шт	 C 712 (3,55 z) Мз 6x3-2шт Ф1.5-10шт Ф1.25-20шт
 C 713 (4,28 z) ф1.5 - 6шт, ф2.0 - 6шт, ф 1.75 - 6шт	 C 714 (4,32 z) ф1.25 - 28шт, ф3.0 - 2шт	 C 715 (11,81 z) ф1.25 - 8шт, ф 1.5 - 26шт, ф10 - 2шт	 C 716 (5,7 z) Ов 8x6-2шт Ф2.5-4шт Ф1.25-38шт
 C 717 (4,04 z) ф1.0 - 82шт	 C 718 (5,31 z) ф2.0 - 14шт, ф1.75 - 4шт, ф1.5 - 2шт, Ов 5x3 - 2шт	 C 719 (5,48 z) ф1.25 - 90шт, ф2.0 - 2шт, ф3.0 - 6шт	 C 720 (4,83 z) ф1.25 - 90шт, Ж4.0 - 2шт, ф3.0 - 6шт

C-37



??????.

??????? : ??? ???? ???????
????
????

[??????? ??????? ?? ????? ???????](#)

????????
?????????
???????? 3.
??????.