

? 45/ ??????? ?3

			
C 861 (4,5 z) ф1.5 - 22шт	C 862 (2,0 z) ф2.0 - 2шт	C 863 (6,45 z) ф6 - 4шт ф7 - 2шт	C 864 (3,36 z) ф2.25-4шт Ж 15-2шт
			
C 865 (13,2 z) ф3.25-6шт ф1.5-28шт ф1.75-12шт ф2.5-2шт ф2.25-2шт ф2-4шт М37х3.5-4шт	C 866 (4,5 z) ф1-34шт Bullet7.5-2шт	C 867 (3,87 z) ф1.5-2шт ф1.25-28шт	C 868 (4,04 z) М3 5х2.5-18шт
			
C 869 (6,85 z) ф1.5-8шт ф1.75-4шт ф2.5-2шт ф2.75-2шт Об6х4-2шт Per13.25-6шт	C 870 (8,05 z) ф1.5-8шт ф1.75-8шт Bullet6-2шт	C 871 (7,29 z) ф1.25-22шт ф5-2шт	C 872 (6,28 z) ф1-8шт ф1.25-8шт ф1.5-4шт Bullet8-2шт
			
C 873 (3,22 z) ф1.5-10шт Об5х3-2шт	C 874 (3,03 z) ф1.25-14шт	C 875 (2,89 z) ф1-10шт	C 876 (3,98 z) ф1.25-24шт М35х2.5-6шт
			
C 877 (4,0 z) ф1.5-10шт Об5х3-4шт	C 878 (3,01 z) ф1.5-6шт	C 879 (5,93 z) Ж7 - 2шт	C 880 (3,70 z) ф1.75 - 12шт, Кв 3 - 2шт

C-45



??????.

??????? : ??? ????
???
???

[?????? ?????? ?? ????? ??????](#)

??????
???????.
?????? 3.
?????.