

? 11

Гарнитур

|                                                                                                                                                      |                                                                                                                                           |                                                                                                                                    |                                                                                                                               |                                                                                                                              |                                                                                                                               |
|------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------|
| <br>20026 2.78<br>М-38х4-1;<br>кр.1,5-1;<br>кр.1,75-2;<br>кр.2,0-2. | <br>40013 3.66 г<br>М-36х3-2;<br>кр.1,75-2;<br>кр.1,5-8. | <br>20042 1.64 г<br>Кр.1,75-1;<br>кр.1,5-3.       | <br>40063 2.88 г<br>Кр.1,75-2;<br>кр.1,5-4.  | <br>20045 3.82 г<br>Кр.2,0-9.               | <br>40123 3.24 г<br>Кр.2,0-18                |
| <br>20046 1.38 г<br>Кр.2,0-1; кр.1,5-6.                             | <br>40064 2.52 г<br>Кр.2,0-2;<br>кр.1,5-12.              | <br>20057 1.69 г<br>М-34х2-5;<br>кр.1,75-1.       | <br>60031 0.85 г<br>М-34х2-5;<br>кр.2,0-1    | <br>20059 1.54 г<br>Кр.1,75-17.             | <br>40048 3.5 г<br>Кр.2,0-20.                |
| <br>20067 1.17 г<br>Кр.1,5-4.                                       | <br>40051 1.96 г<br>Кр.1,5-8.                            | <br>20069 1.41 г<br>Кр.1,5-3.                     | <br>40050 2.1 г<br>Кр.1,5-6.                 | <br>20070 0.9 г<br>Кр.1,5-4;<br>жемч.4,0-1. | <br>40065 1.96 г<br>Кр.1,5-8;<br>жемч.3,0-2. |
| <br>20081 1.45 г<br>М-34х2-3                                        | <br>40070 2.3 г<br>М-34х2-6.                             | <br>20085 1.9 г<br>Кр.1,75-1;<br>жемч.4,0-1.      | <br>40071 2.86 г<br>Кр.1,5-4;<br>жемч.4,0-2. | <br>20091 3.4 г<br>Треуг.усеч.Н9-1.         | <br>40073 5.6 г<br>Треуг.усеч.Н9-2.          |
| <br>20095 2.14 г<br>Кр.4,0-1;<br>кр.2,0-8.                        | <br>40115 3.25 г<br>Кр.4,0-2;<br>кр.1,5-16             | <br>20096 2.35 г<br>Ов 6х4-1;<br>кр.2,0-10      | <br>40102 2.8 г<br>Ов.6х4-2; кр.1,5-20     | <br>20103 1.34 г<br>Кр.2,0-1.             | <br>40112 1.96 г<br>Кр.2,0-2               |
| <br>20108 2.02 г<br>Кр.3,0-1;<br>кр.2,0-18.                       | <br>40099 3.2 г<br>Кр.3,0-2;<br>кр.1,75 -36            | <br>20116 2.7 г<br>Треуг.Н10(9)-1;<br>кр.1,5-3. | <br>40186 3.68 г<br>Треуг.9-2;<br>кр.1,5-6 | <br>20126 3.09 г<br>Кр.3,0-5.             | <br>40107 2.96 г<br>Кр.3,0-8               |



?????????

??????? : ??? ? ? ? ? ? ? ? ?  
????  
????

[??????? ???? ? ? ? ? ? ? ? ?](#)

????????

????????.

???????? 2.

????????.