


? 38/ ??????? ?3

 C 721 (4,89 з) Гр 8х5-2шт Ф1.25-20шт	 C 722 (5,23 з) Кв2х2 - 6шт, Гр5х3 - 6шт, Ф1.5 - 6шт	 C 723 (5,94 з) Ф1.75 - 22шт, Ф2.0 - 8шт	 C 724 (3,33 з) Ф1.5 - 38шт
 C 725 (4,63 з) Ф1.5 - 38шт, Ф1.25 - 20шт	 C 726 (4,81 з) М35х2.5 - 16шт, Ф1.75 - 4шт, Ф1.25 - 8шт	 C 727 (3,19 з) Ф1.5 - 12шт, Ф1.25 - 18шт	 C 728 (4,25 з) Кв6-2шт
 C 729 (4,73 з) Ф7-2шт	 C 730 (4,08 з) Ф3-2шт Ф2-6шт Ф1.5-4шт	 C 731 (2,7 з) Ф2-4шт Ф1.5-10шт	 C 732 (2,6 з) Ф3.25-2шт Ф1.75-6шт
 C 733 (4,55 з) М3 5х2.5-6шт	 C 734 (4,18 з) Ф3.75-2шт Ф2.25-4шт	 C 735 (3,32 з) Ф2.25-4шт	 C 736 (5,32 з) Ф2.75-8шт Ов8х6-2шт
 C 737 (4,6 з) Ф1.25-8шт М39х4.5-2шт	 C 738 (5,23 з) Ф2-10шт Ф2.75-4шт Ф5.25-2шт	 C 739 (6,57 з) Ф3.25-6шт Кв4.5-2шт Кв5.5-2шт	 C 740 (5,04 з) Ф2-10шт Кв4.5-2шт Кв5.5-2шт

C-38



??????.

??????? : ??? ???? ???????
????
????

[?????? ?????? ?? ????? ??????](#)

???????

???????

?????? 3.

?????.