

? 42/ ??????? ?3



C 801 (2,26 з)
Ф1.75-6шт



C 802 (2,83 з)
Ф2-30шт



C 803 (2,7 з)
Ф1.25-16шт Ф1.5-8шт



C 804 (2,77 з)
Ф1.25-2шт Ф2.5-2шт



C 805 (2,69 з)
Ф1-4шт Ф1.25-2шт Ф1.5-16шт



C 806 (2,54 з)
Ф1.5-8шт Ф2-2шт



C 807 (3,8 з)
Ф3.25-2шт Ф1- 14шт Ф1.25-16шт



C 808 (3,61 з)
Ф1.25 - 8шт Ф1.5 - 8шт



C 809 (3,12 з)
Ф3-2шт Ф1.25-4шт Ф1.75-4шт



C 810 (3,67 з)
Ф1.5-2шт Гр5х3-10шт



C 811 (5,4 з)
Гр 8х5 - 2шт Ф3 - 2шт Ф2 - 4шт
Ф1.75 - 4шт Ф1.5 - 4шт Ф1.25 - 4шт



C 812 (2,72 з)
Ф1.25-32шт



C 813 (2,82 з)
Ф2-4шт Ов5х3-4шт



C 814 (5,19 з)
Ф1.5-12шт Ф2.25-6шт
Ов6х4-6шт




C 815 (9,09 з)
Ф1.25-10шт М34х2-10шт
Трп5.5-10шт



C 816 (3,8 з)
Ф1-22шт Гр5х3-2шт



C 817 (3,73 з)
Ф1-4шт Ф1.5-4шт Ф1.75-4шт



C 818 (3,2 з)
Ф1-18шт Ф1.25-8шт



C 819 (3,24 з)
Ф1.25-70шт Ф1.5 - 4шт
Ф1.75 - 4шт



C 820 (4,05 з)
Ф3-14шт

C-42



??????.

??????? : ??? ??? ???????
????
????

[?????? ?????? ?? ????? ??????](#)

???????

???????

?????? 3.

?????.